

Three Empire State Plaza, Albany, NY 12223-1350 www.dps.ny.gov

#### **Public Service Commission**

Rory M. Christian Chair and Chief Executive Officer

> Diane X. Burman James S. Alesi Tracey A. Edwards John B. Howard David J. Valesky John B. Maggiore Commissioners

September 21, 2023

**VIA EMAIL** 

Hon. Michelle L. Phillips Secretary to the Commission 3 Empire State Plaza Albany, NY 12223-1350

Re: Matter No. 21-01188 – In the Matter of the Indian Point Closure Task Force and Indian Point Decommissioning Oversight Board.

Dear Secretary Phillips:

Please accept for filing in the above-captioned matter, independent technical expert Dave Lochbaum's September 21, 2023 presentation to the Indian Point Decommissioning Oversight Board regarding independent spent fuel storage installation inspections. Should you have any questions regarding this filing, please contact me. Thank you.

Respectfully submitted,

don Jul

Tom Kaczmarek Executive Director Indian Point Closure Task Force Indian Point Decommissioning Oversight Board

# Indian Point

**Independent Spent Fuel Storage Installation** (a.k.a. Onsite Dry Storage of Spent Fuel)





## Terminology

Spent fuel assemblies are loaded into a canister that is sealed. The canister is then placed inside a concrete and steel cask. Air flows through the space between the canister and cask to remove the spent fuel's decay heat.

Inspections review procedures, test results, etc. and observe work to check compliance. Examinations look at canisters' outer surfaces for indications of degradation. Special Inquity into the U.S. Nuclear Regulatory Commission Region II's Inspections of Independent Spent Fuel Storage Installations at Operating Reactors

Set OF THE INSPECTOR,

AR REGULATORY C

Responding to allegations from an NRC worker, the NRC's Office of the Inspector General (OIG) looked into how NRC Region II (southeast USA) assessed ISFSI safety.

OIG's report was issued in February 2023.

#### IV. DETAILS

### Finding: Region II's past inspection practice resulted in missed opportunities to identify ISFSI violations

Through this Special Inquiry, the OIG determined that Region II's inspections of repeat loading campaigns from 2012 through 2020 deviated from NRC policies in that (1) resident inspectors did not obtain ISFSI qualifications before inspecting ISFSIs, and (2) Region II likely did not fully meet ISFSI inspection requirements based on the actual number of inspection hours charged. Fully qualified ISFSI inspectors began inspecting Region II ISFSIs in 2021, and since then, those inspectors have found multiple ISFSI violations that might have been detected earlier; however, there are still a significant number of loaded casks that have not been properly inspected.

Figure 6: Region II ISFSI inspection hours for repeat loading campaigns

	2018	2019	
Region II inspection hours charged to IP 60855.1	231	273	_
Spent Fuel Loading Campaigns at Region II plants	14	12	
Percentage of inspection hours compared to estimated 100 hours per campaign resourced in IP 60855.1	15%	20%	

Source: OIG generated from Region II assessment

Region II inspectors confirmed that the hours they spent inspecting repeat loading campaigns were far fewer than those estimated in IP 60855.1, and some stated that, in their view, inspection requirements were not fully met. A Region II principal stated that OIG found that NRC Region II was using unqualified inspectors who performed 20 percent or less of the specified dry cask storage inspection scope. After the OIG report was issued, I reviewed dry cask loadings at Indian Point and NRC's oversight efforts.

As of February 1, 2023, 81 casks containing 2,592 fuel assemblies had been loaded at Indian Point.

I found 14 publicly available NRC inspection reports for ISFSI operations at Indian Pont between 2010 and 2023. The reports documented NRC's observation of several canister loadings.

What those inspection reports did not reveal:

- How many inspection hours were devoted to the inspections?
- While the names of the NRC inspectors were listed in the inspection reports, their qualifications were not provided. Were all these inspectors fully qualified to perform ISFSI inspections?



Thomas Congdon Chair

August 31, 2023

Via Email

Douglas Tifft State Liaison Officer, Region 1 U.S. Nuclear Regulatory Commission 475 Allendale Road, Suite 102 King of Prussia, PA 19406-1415 doug.tifft@nrc.gov

#### Re: ISFSI Inspection and OIG Report

Dear Mr. Tifft,

The Indian Point Decommissioning Oversight Board was recently made aware of an issue concerning NRC oversight and inspections of spent nuclear fuel storage. In February 2023, the Nuclear Regulatory Commission's Office of the Inspector General (OIG) issued a report on its audit of the U.S. Nuclear Regulatory Commission (NRC) Region II's oversight of Independent Spent Fuel Storage Installations (ISFSIs).<sup>1</sup> OIG's chief findings were that NRC Region II, which covers the southeast states, used unqualified inspectors between 2012 and 2020 for dry cask oversight and the inspectors used less than 20 percent of the hours specified to adequately perform the dry cask inspections.

The Indian Point DOB has requested that NRC Region I formally explain whether its ISFSI inspections at Indian Point and other nuclear plants in the state were conducted by qualified inspectors who performed full-scope inspections.



## Why It Matters

Risk over lifetime is defined by the Bathtub Curve. Material imperfections, assembly errors, operator mistakes, etc. cause the failure rate during the "break-in" phase to be relatively high.

	Figure 8: Region II issued ISFSI violations in 2021 and 2022			
	Violation	Description		
1	Severity Level IV, NCV of 10 C.F.R. Part 72.162, "Test Control." (ADAMS Accession No. ML22308A179)	Failure to incorporate the design basis flow rates for the Forced Air Cooling units into ongoing testing procedures or other instructions to ensure the criteria in FSAR Section 4.2 for the fuel cladding and the various components of the transfer casks were satisfied.		
2	Severity Level IV NCV of 10 C.F.R. 72.48(d)(1),6, "Changes, Tests, and Experiments." (ADAMS Accession No. ML22308A179)	Failure to provide the basis for the determination that the presence of boiling water in the dry shielded canister and transfer cask annulus does not require a CoC amendment.		
3	Green finding and associated NCV of Title 10, C.F.R. Part 50, Appendix B, Criterion III, "Design Control." (ADAMS Accession No. ML22130A795)	Failure to develop appropriate acceptance criteria associated with the ISPSI haul path and the railway access hatch hoisting system and failed to verify the adequacy of the Auxiliary Building Crane testing program.		
4	Green finding and associated NCV of Title 10, C.F.R. Part 50, Appendix B, Criterion III, "Design Control." (ADAMS Accession No. ML22132A308)	Failure to translate the maximum cask lift elevation and the locking of the trunnion axis into site procedures.		
5	Green finding and associated NCV of 10 C.F.R. Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings." (ADAMS Accession No. ML21314A186)	When procedure 0-TI-561, "Underground Piping and Tanks Integrity Program," (a procedure described in the UFSAR) was changed, the licensee failed to perform the 10 C.F.R. 50.59 evaluation to determine whether the calculation "Evaluation of Cask Transporter Haul Route ([]Report []- 2022947 for the Dry Cask Storage Project)" continued to demonstrate that ISPSI operations will not compromise plant underground safe shutdown equipment.		
6	Green finding and associated NCV of 10 C.F.R. Part 50, Appendix B, Criterion III, "Design Control." (ADAMS Accession No. ML21314A530)	Failure to translate applicable acceptance criteria for the spent fuel bridge crane into its plant maintenance procedure.		

When NRC Region II resumed using qualified inspectors performing full-scope dry cask storage inspections, many safety violations during the "break-in phase" at Region II plants were readily identified.

What about the righthand side of the Bathtub Curve, the "wear-out" phase where failure rate increases?



All Dry Cask Storage Systems (DCSS) are headed towards, if not already in, the wear-out portion of the Bathtub Cure where chloride-induced stress corrosion cracking is the primary aging degradation concern.



Managing Aging Processes in Storage (MAPS) calls for examinations every five years. Industry typically plans to examine one, maybe two, "most vulnerable" canisters over and over to facilitate trending of degradation results.



"Most vulnerable" is defined by nearness to salt spray (e.g., deposition), canister metal type, and decay heat levels of spent fuel inside canisters.

![](_page_12_Figure_0.jpeg)

"Most vulnerable" should also consider pre-existing gouges, scratches, etc. on canister walls that facilitate initiation of chloride-induced stress corrosion cracking.

![](_page_13_Figure_0.jpeg)

Not unlike how a small chip in a car's windshield spawns a widening crack, a surface crack aids the initiation and propagation of metal cracking.

![](_page_14_Figure_0.jpeg)

HOLTEC concedes that surface scratches in its dry casks and canisters are everywhere and commonplace.

![](_page_15_Figure_0.jpeg)

HOLTEC contends that canister surface scratches "*are not relevant to the safety determination*" despite being a factor in the primary aging degradation mechanism.

![](_page_16_Figure_0.jpeg)

NRC needs to perform full-scope ISFSI inspections using qualified inspectors. Periodic examinations of dry cask storage systems must be based on science rather than convenience.

![](_page_17_Figure_0.jpeg)

The State's agreement with HOLTEC accelerated transfers from the spent fuel pools to the ISFSI pads. While not zero risk, the ISFSI poses significantly lower risk than a spent fuel pool. Each canister holds 32 fuel assemblies. Each spent fuel pool held several hundred assemblies. Lower energy levels and lesser amounts of radioactivity in each canister translates into lower risk.

Should a thru-wall crack form in a canister wall, little to no radiation will leak out. The crack will require patching to restore integrity and structural strength before the canister is moved.