

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
1

Date:
5/9/12

Direction Photo Taken:

West

Description:

Honeysuckle in typical view of project corridor edge.



Photo No.
2

Date:
5/9/12

Direction Photo Taken:

East

Description:

Honeysuckle in typical view of project corridor edge.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
3

Date:
5/9/12

Direction Photo Taken:

Southeast

Description:

Honeysuckle in typical view of project corridor edge.



Photo No.
4

Date:
5/9/12

Direction Photo Taken:

South

Description:

Typical small area of teasel and garlic mustard within project corridor.



Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
5

Date:
5/9/12

Direction Photo Taken:

West

Description:

Small area of garlic mustard within project corridor (Hickory Grove road through trees).



Photo No.
6

Date:
5/9/12

Direction Photo Taken:

Northwest

Description:

Typical view of honeysuckle and multiflora rose along project corridor boundary.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
7

Date:
5/9/12

Direction Photo Taken:

North

Description:

Small area of teasel within project corridor, honeysuckle and multiflora rose in background along edge of corridor.



Photo No.
8

Date:
5/9/12

Direction Photo Taken:

North

Description:

Small area of teasel, typical view of honeysuckle along edge of project corridor.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
9

Date:
5/9/12

Direction Photo
Taken:

West

Description:

Typical view of project
corridor with
honeysuckle on either
side.



Photo No.
10

Date:
5/9/12

Direction Photo
Taken:

West

Description:

Small area of
reed
canarygrass within
project corridor.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
11

Date:
5/9/12

Direction Photo Taken:

North

Description:

Small area of reed canarygrass within project corridor.



Photo No.
12

Date:
5/9/12

Direction Photo Taken:

West

Description:

Typical view of maintained right-of-way and small growth of teasel within project corridor.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
13

Date:
5/9/12

Direction Photo Taken:

Northeast

Description:

Typical shrub honeysuckle along edge of project corridor.



Photo No.
14

Date:
5/9/12

Direction Photo Taken:

Northwest

Description:

Typical view of edge of maintained right-of-way and edge of project corridor.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
15

Date:
5/9/12

Direction Photo Taken:

North

Description:

Typical view of edge of project corridor, with teasel, honeysuckle, multiflora rose.



Photo No.
16

Date:
5/9/12

Direction Photo Taken:

North

Description:

Typical view of edge of project corridor, with teasel, honeysuckle and multiflora rose.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
17

Date:
5/9/12

Direction Photo Taken:

Southwest

Description:

Typical view of maintained right-of-way and honeysuckle along edge of project corridor.



Photo No.
18

Date:
5/9/12

Direction Photo Taken:

Northeast

Description:

Small multiflora rose shrubs within project corridor.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
19

Date:
5/9/12

Direction Photo Taken:

West

Description:

Typical view of edge of project corridor, showing honeysuckle.



Photo No.
20

Date:
5/9/12

Direction Photo Taken:

Northeast

Description:

Typical view of maintained right-of-way and edge of project corridor, showing honeysuckle.



Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
21

Date:
5/9/12

Direction Photo Taken:

Southwest

Description:

Typical view of edge of project corridor, showing multiflora rose, honeysuckle and garlic mustard.



Photo No.
22

Date:
5/9/12

Direction Photo Taken:

southwest

Description:

Small area of teasel along edge of project corridor.





PHOTOGRAPHIC LOG

Client Name: NYSEG		Site Location: Horseheads, New York	URS Project No. 11176689
Photo No. 23	Date: 5/9/12		
Direction Photo Taken: Southwest			
Description: Garlic mustard along edge of project corridor.			

Photo No. 24	Date: 5/9/12		
Direction Photo Taken: West			
Description: Garlic mustard and honeysuckle.			

Client Name: NYSEG		Site Location: Horseheads, New York	URS Project No. 11176689
Photo No. 25	Date: 5/9/12		
Direction Photo Taken: Southwest			
Description: Honeysuckle, garlic mustard, multiflora rose within project corridor.			

Photo No. 26	Date: 5/9/12		
Direction Photo Taken: West			
Description: Honeysuckle, garlic mustard, multiflora rose within project corridor.			

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
27

Date:
5/9/12

Direction Photo Taken:

Southeast

Description:

Typical multiflora rose within project corridor, honeysuckle along edge.



Photo No.
28

Date:
5/9/12

Direction Photo Taken:

West

Description:

Typical multiflora rose within project corridor.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
29

Date:
5/9/12

Direction Photo Taken:

West

Description:

Typical view of honeysuckle and multiflora rose along project corridor.



Photo No.
30

Date:
5/9/12

Direction Photo Taken:

West

Description:

Typical view of project corridor, with honeysuckle in view.



Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
31

Date:
5/9/12

Direction Photo Taken:

Northeast

Description:

Typical view of edge of corridor, showing honeysuckle and small area of teasel.



Photo No.
32

Date:
5/9/12

Direction Photo Taken:

Northwest

Description:

Reed canarygrass within project corridor.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
33

Date:
5/9/12

Direction Photo Taken:

South

Description:

Typical view of edge of project corridor.



Photo No.
34

Date:
5/9/12

Direction Photo Taken:

East

Description:

Teasel within project corridor.



Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
35

Date:
5/9/12

Direction Photo Taken:

Northwest

Description:

Japanese knotweed adjacent to project corridor.



Photo No.
36

Date:
5/9/12

Direction Photo Taken:

Southeast

Description:

Japanese knotweed within project corridor.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
37

Date:
5/9/12

Direction Photo Taken:

South

Description:

Japanese knotweed adjacent to project corridor.



Photo No.
38

Date:
5/9/12

Direction Photo Taken:

Southwest

Description:

Typical view of teasel, multiflora rose and honeysuckle (background).



Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
39

Date:
5/9/12

Direction Photo Taken:

East

Description:

Teasel.



Photo No.
40

Date:
5/9/12

Direction Photo Taken:

South

Description:

Typical view of edge of project corridor, showing honeysuckle.





PHOTOGRAPHIC LOG

Client Name: NYSEG

Site Location: Horseheads, New York

URS Project No.

11176689

Photo No.
41

Date:
5/9/12

Direction Photo Taken:

Northwest

Description:

Typical view of edge of project corridor, showing multiflora rose.

