

National Grid Visually Failed Fusion Report - November 2025  
Attachment 3 - NIMO

| NIMO                                                               |                                 |            |            |           |                             |                |                     |                             |                 |                                          |                  |               |                      |                 |                |                             |
|--------------------------------------------------------------------|---------------------------------|------------|------------|-----------|-----------------------------|----------------|---------------------|-----------------------------|-----------------|------------------------------------------|------------------|---------------|----------------------|-----------------|----------------|-----------------------------|
| Monthly Report of Failed Fuses Inspected in November               |                                 |            |            |           |                             |                |                     |                             |                 |                                          |                  |               |                      |                 |                |                             |
| Object ID                                                          | Fuser                           | Pipe Type  | Pipe Size  | Fuse Type | Visual Inspection Pass/Fail | Electrofuse ID | Remediation Taken   | Destructive Testing Results | Main or Service | Street                                   | City             | Contractor Co | Location Type        | Inspection Date | Installed Date | Status                      |
| 102696                                                             | Existing Fuse - Inspection Only | HD         | 2          | MBF       | Fail                        | MBF            | Cutout              | TBD                         | MAIN            | 1076 Madison St                          | Syracuse         | NationalGrid  | InServiceFuse        | 11/24/2025      | 2025           | Cutout                      |
| 102548                                                             | Existing Fuse - Inspection Only | HD         | 4          | Sidewall  | Fail                        | Sidewall       | Cutout              | TBD                         | MAIN            | 5369 Fortuna Pkwy                        | Clay             | NationalGrid  | VintageInServiceFuse | 11/20/2025      | 2025           | Cutout                      |
| PREVIOUSLY REPORTED INSERVICE FUSES WHICH FAILED VISUAL INSPECTION |                                 |            |            |           |                             |                |                     |                             |                 |                                          |                  |               |                      |                 |                |                             |
| OBJECTID                                                           | FUSER                           | PIPE_TYP E | PIPE_SIZ E | FUSE_TYPE | VISUAL_INSP_PASS            | ELECTROFUSE_ID | REMEDIA TION _TAKEN | DESTRUCTIVE TESTING RESULTS | MAIN_OR_SERVICE | REV_STREET                               | REV_CITY         | CONTRACTCO    | LOCATIONTYPE         | INSPECTION DATE | INSTALLED DATE | STATUS                      |
| 101281                                                             | Existing Fuse - Inspection Only | HD         | 6          | Butt      | Fail                        | 6" In Line Tee | Repair Scheduled    | TBD                         | Main            | 3 N Holmes St                            | Schenectady      | NationalGrid  | InServiceFuse        | 10/9/2025       | 2025           | 30 Day Leak Survey No Leaks |
| 101618                                                             | Existing Fuse - Inspection Only | HD         | 2          | Sidewall  | Fail                        | Sidewall       | Repair Scheduled    | TBD                         | Service         | 4110 Bermond Ct                          | Liverpool        | NationalGrid  | VintageInServiceFuse | 10/17/2025      | 1971           | 30 Day Leak Survey No Leaks |
| 101692                                                             | Existing Fuse - Inspection Only | HD         | 2          | Sidewall  | Fail                        | Sidewall       | Repair Scheduled    | TBD                         | Service         | 4976 Blacksmith Path                     | Liverpool        | NationalGrid  | VintageInServiceFuse | 10/21/2025      | 1975           | 30 Day Leak Survey No Leaks |
| 100765                                                             | Existing Fuse - Inspection Only | HD         | 6          | HBF       | Fail                        | HBF            | Cutout              | TBD                         | Main            | Mile 7.6 State Hwy 5                     | Schenectady      | NationalGrid  | InServiceFuse        | 9/23/2025       | 2025           | Cutout                      |
| 100470                                                             | Existing Fuse - Inspection Only | HD         | 0.5        | MBF       | Fail                        | MBF            | Cutout              | Failed                      | Service         | 8 Mourningkill Dr (AKA 1284 Saratoga Rd) | Ballston Spa     | NationalGrid  | VintageInServiceFuse | 9/17/2025       | 1974           | Cutout                      |
| 100217                                                             | Existing Fuse - Inspection Only | HD         | 2          | Sidewall  | Fail                        | Sidewall       | Repair Scheduled    | TBD                         | Main            | 658 Old Liverpool Rd                     | Liverpool        | NationalGrid  | VintageInServiceFuse | 9/4/2025        | 1983           | 30 Day Leak Survey No Leaks |
| 100369                                                             | Existing Fuse - Inspection Only | HD         | 0.5        | Sidewall  | Fail                        | Sidewall       | Cutout              | TBD                         | Service         | 21 Wampum Dr                             | Saratoga Springs | NationalGrid  | VintageInServiceFuse | 9/12/2025       | 1972           | Cutout                      |
| 100469                                                             | Existing Fuse - Inspection Only | HD         | 0.5        | Sidewall  | Fail                        | Sidewall       | Cutout              | Failed                      | Service         | 8 Mourningkill Dr (AKA 1284 Saratoga Rd) | Ballston Spa     | NationalGrid  | VintageInServiceFuse | 9/12/2025       | 1974           | Cutout                      |
| 100026                                                             | Existing Fuse - Inspection Only | HD         | 2          | Sidewall  | Fail                        | Sidewall       | Repair Scheduled    | TBD                         | Main            | 25 Westbrook Hills Dr (4950)             | Syracuse         | NationalGrid  | VintageInServiceFuse | 8/29/2025       | 1973           | 30 Day Leak Survey No Leaks |
| 100025                                                             | Existing Fuse - Inspection Only | HD         | 2          | Sidewall  | Fail                        | Sidewall       | Repair Scheduled    | TBD                         | Main            | 25 Westbrook Hills Dr (4950)             | Syracuse         | NationalGrid  | VintageInServiceFuse | 8/29/2025       | 1973           | 30 Day Leak Survey No Leaks |
| 99427                                                              | Existing Fuse - Inspection Only | HD         | 0.5        | Socket    | Fail                        | Socket         | Cutout              | TBD                         | Service         | 748 Taft Ave                             | Syracuse         | NationalGrid  | VintageInServiceFuse | 8/12/2025       | 1974           | Cutout                      |
| 99348                                                              | Existing Fuse - Inspection Only | HD         | 4          | Sidewall  | Fail                        | Sidewall       | Cutout              | TBD                         | Main            | 510 Fay Ln                               | Minoa            | NationalGrid  | VintageInServiceFuse | 8/7/2025        | 1973           | Cutout                      |