

nationalgrid

EXECUTIVE
PUBLIC SERVICE
COMMISSION
ALBANY

January 26, 2017 2017 JAN 27 AM 11:02

Hon. Kathleen H. Burgess
Secretary to the Commission
New York State Public Service Commission
Empire State Plaza
Agency Building 3
Albany NY 12223-1350

Re: National Grid Report of PCB Containing Materials in the Gas Distribution System

Dear Secretary Burgess:

In accordance with 16 NYCRR Part 730.1(c), the NYS Public Service Law requires that National Grid provide an annual report on the discovery of materials in the gas distribution system, containing PCBs in concentrations 50 parts per million (ppm) or greater, to the Albany office of the Energy and Water Division.

Attached please find a report of such discoveries for the following National Grid companies:

- Niagara Mohawk Power Corporation d/b/a National Grid
- KeySpan Gas East Corporation d/b/a National Grid
- Brooklyn Union Gas Company d/b/a National Grid NY

If you have any questions, please contact me at 315-428-6685.

Sincerely,



Philip B George
Manager-Environmental

Cc: C. Corrado, National Grid

National Grid
Report of Materials Containing ≥50ppm PCB in the Gas Distribution System
in accordance with 16 NYCRR Part 730.1(c)
January 1, 2016 to December 31, 2016

Niagara Mohawk Power Corporation d/b/a National Grid

<u>Location</u>	<u>Collection Point</u>	<u>Date of Delivery</u>	<u>Date of Removal</u>	<u>Volume Removed</u>	<u>PCB Concentration (ppm)</u>	<u>Source</u>	<u>Method of Removal</u>
28 Smith Bridge Road, Saratoga Springs, NY	Gas Pipe Cleanout / Filter	9/26/2016	9/26/2016	5 kg	74	Natural gas service line / Filter	Routine maintenance

KeySpan Gas East Corporation d/b/a National Grid

296 Lake Ave, St James, NY	Distribution Pipe	N/A	2/15/2016	3 gal	574	Oil in gas system	Physical Excavation
298 Adams Ave, Farmingdale, NY	Regulator, Meter & Various Fittings	N/A	4/5/2016	Not Measured / De minimis	140	Dust in gas system	Filter Installed

Brooklyn Union Gas Company d/b/a National Grid NY

88-10 35th Ave, Queens, NY	Strainer	N/A	1/5/2016	Not Measured / De minimis	52.8	Strainer	Manual
247 Thomas S. Boyland St, Brooklyn, NY	Strainer	N/A	2/9/2016	Not Measured / De minimis	161	Strainer	Manual
3965 52 St, Flushing, NY	Strainer	N/A	2/19/2016	Not Measured / De minimis	90.6	Strainer	Manual
660 East 98 Street, Brooklyn, NY	Strainer	N/A	2/24/2016	Not Measured / De minimis	308	Strainer	Manual
37 New Lots Ave, Brooklyn, NY	Strainer	N/A	4/7/2016	Not Measured / De minimis	1360	Strainer	Manual
770 Broadway, Brooklyn, NY	Strainer	N/A	4/11/2016	Not Measured / De minimis	336	Strainer	Manual
34-31 77 Street, Queens, NY	Strainer	N/A	4/27/2016	Not Measured / De minimis	175	Strainer	Manual
883 Classon Ave, Brooklyn, NY	Strainer	N/A	5/4/2016	Not Measured / De minimis	417	Strainer	Manual
315 Sutter Ave, Brooklyn, NY	Strainer	N/A	5/18/2016	Not Measured / De minimis	3850	Strainer	Manual
1580 E. 13 St, Brooklyn, NY	Strainer	N/A	5/18/2016	Not Measured / De minimis	659	Strainer	Manual

<u>Location</u>	<u>Collection Point</u>	<u>Date of Delivery</u>	<u>Date of Removal</u>	<u>Volume Removed</u>	<u>PCB Concentration (ppm)</u>	<u>Source</u>	<u>Method of Removal</u>
271 Caoman Plaza East, Brooklyn	Strainer	N/A	5/18/2016	Not Measured / De minimis	118	Strainer	Manual
3611 14 Ave, Brooklyn, NY	Strainer	N/A	5/18/2016	Not Measured / De minimis	68.9	Strainer	Manual
8510 120th Street, Queens NY	Strainer	N/A	6/9/2016	Not Measured / De minimis	114	Strainer	Manual
9 Monument Walk, Brooklyn, NY	Strainer	N/A	9/29/2016	Not Measured / De minimis	73	Strainer	Manual
845 Gates Ave Brooklyn NY	Strainer	N/A	10/28/2016	Not Measured / De minimis	81.6	Strainer	Manual
65-30 108th Street, Queens NY	Strainer	N/A	12/13/2016	Not Measured / De minimis	70.9	Strainer	Manual