

**Consolidated Edison Company of New York, Inc.  
2013 Gas Rate Case: Listing of Open  
Appendix B Sites**

**Exhibit \_\_\_(RSP-4)  
Page 1 of 2**

<b>Site</b>	<b>Priority*</b>	<b>Site Name</b>	<b>Location</b>	<b>Con Ed Facility?</b>	<b>Status (as of 6/30/12)</b>
1	Medium	10th St./ 37-38th Ave.	QN	No	Field investigation completed; investigation report submitted to DEC; supplemental investigation will be required. Combined with Site 79.
2	**	East River Complex	MN	Partially	Initial investigation completed; investigation report under DEC review; a supplemental investigation and some remediation will be required.
4	High	38th-39th Ave./ 21st St.	QN	No	Field investigation completed; investigation report submitted to DEC; supplemental investigation will be required. Combined with Site 79.
4a	**	LIC Subway/12th St. & 41st Ave.	QN	No	On going groundwater monitoring.
7a	High	Pipeline 2/E71st St.	MN	No	Investigation Work Plan approved; field investigation pending. Will be addressed in conjunction with fuel oil pipeline closure activities
9	Medium	Astoria Blvd/ 78th Street	QN	No	Investigation Work Plan submitted to DEC.
10	**	Astoria Site	QN	Yes	Investigation and remediation ongoing. Addressed separately under hazardous waste permit.
12	High	Farragut Substation & Vicinity	BK	Partially	Initial investigation completed; investigation report and remediation plan submitted to DEC, which provided comments; supplemental investigation and some remediation will be required.
14	**	Hudson Avenue Station	BK	Yes	Investigation completed; product recovery and hydraulic control systems operating; soil excavation will be required in some areas.
19	Medium	12th Ave./ 40th St - W49th St. Substation	MN	Partially	Dielectric fluid related to an historic spill encountered during feeder repair; recovery system installed and product recovery ongoing. Additional investigation is required. Work plan submitted to DEC.
20	**	Hellgate Substation/Locust Ave./132nd St/133rd St.	BX	Partially	Groundwater monitoring ongoing.
22	Low	Westchester Ave./ St. Ann's Ave.	BX	No	Investigation Work Plan being prepared
23	Medium	E 25th St./ FDR	MN	No	Investigation Work Plan submitted to DEC.
26	**	54-08 Vernon Boulevard	QN	No	Field investigation completed; investigation report submitted to DEC; supplemental investigation will be required. Combined with Site 79.
28	Medium	W 54th St./ 11th Ave.	MN	No	Investigation Work Plan submitted to DEC.
30	Low	Meeker Avenue/ Leonard Street	BK	No	Investigation Work Plan submitted to DEC.
33	Low	79th St./ 3rd Avenue	BK	No	Investigation Work Plan submitted to DEC.
35	Low	Park Place/ New York Ave.	BK	No	Investigation Work Plan submitted to DEC.
38	Low	52nd St/ 1st. Ave.	BK	No	Investigation Work Plan submitted to DEC, which provided comments that will require Plan revisions..
39	Low	108th St./ 64th Rd.	QN	No	Investigation Work Plan submitted to DEC.
40	**	21st St and 46th Road.	QN	No	Field investigation completed; investigation report submitted to DEC. Additional investigation is required. Combined with Site 79.
49	Low	141st Street/ Brook Avenue	BX	No	Investigation Work Plan submitted to DEC.
56	High	Broadway/141st St./142nd St.	MN	No	Initial investigation completed; investigation report submitted to DEC; supplemental investigation and some remediation will be required per DEC-approved plan.
57	Medium	4th Ave. and Garfield St./ 6th street	BK	No	Investigation Work Plan submitted to DEC.
59	Medium	Jay and Concord Street	BK	No	Investigation Work Plan submitted to DEC.
60	Medium	11th Street Conduit	BK	No	Investigation Work Plan submitted to DEC.
61	Low	Classon And Flushing	BK	No	Investigation Work Plan submitted to DEC.
63	Medium	Wythe Avenue and N13th Street	BK	No	Investigation Work Plan submitted to DEC, which provided comments that will require Plan revisions..
64	Low	St. James btw Gates and Fulton	BK	No	Investigation Work Plan submitted to DEC.
65	Low	E 189th Street and Webster Avenue	BK	No	Investigation Work Plan submitted to DEC.
66	Low	E 233 Street and Webster	BX	No	Investigation Work Plan submitted to DEC.
67	High	E 180th Street and Morris Park Ave.	BX	No	Remediation completed. Remediation report submitted to the DEC, which provided comments and questions.
68	Low	Parkchester-Tremont S/S	BX	No	Investigation Work Plan submitted to DEC.

**Consolidated Edison Company of New York, Inc.  
2013 Gas Rate Case: Listing of Open  
Appendix B Sites**

**Exhibit \_\_\_(RSP-4)  
Page 2 of 2**

<b>Site</b>	<b>Priority*</b>	<b>Site Name</b>	<b>Location</b>	<b>Con Ed Facility?</b>	<b>Status (as of 6/30/12)</b>
69	High	Broadway south of W. 116th St.	MN	No	Initial investigation completed; investigation report submitted to DEC; supplemental investigation and some remediation may be required. Periodic remediation in subway tunnel when oil is found there.
70	Medium	Worth N/O Centre St.	MN	No	Investigation Work Plan submitted to DEC.
71	Medium	W 59th Street and 5th Avenue	MN	No	Investigation Work Plan submitted to DEC.
72	Medium	E Broadway E/O Grand Street	MN	No	Investigation Work Plan submitted to DEC.
73	Medium	W 67th Street w/o Broadway	MN	No	Investigation Work Plan submitted to DEC.
76	Low	Ave A and E 6th Street	MN	No	Investigation Work Plan being prepared
78	Low	11th Avenue and 29th Street	MN	No	Investigation Work Plan being prepared
79	High	Vernon Boulevard & 45th Ave/11th St. & 46th Ave.	QN	No	This investigation is combined with portions of Sites 1, 4, 26, and 40. Field investigation reports submitted. DEC requires additional investigation.
80	Low	Cooper Avenue and 73rd Place	QN	No	Investigation Work Plan submitted to DEC.
83	**	Dunwoodie Substation	WE	Yes	Investigation completed; groundwater monitoring & some product recovery ongoing.
84	**	Elmsford Substation	WE	Yes	Investigation and soil and manhole remediation completed; remediation report has been submitted and approved by DEC. Product recovery ongoing.

\* Per the DEC-approved Site Prioritization Report.

\*\* Not addressed in Site Prioritization Report, since investigation already started or planned.