

Submitter Information

Entity Name:

National Grid

Street Address:

25 Hub Dr.

State:

NY

City:

Melville

Zip Code:

11747

Contact Information

First Name:

Middle Name:

Last Name:

Phone:

Email:

anthony.capozzi@Nationalgrid.com

Alleged Entity Information

Alleged Entity Name:

Vista Contractors Corp.

Street Address:

106 Crescent Ct.

State:

NY

City:

wading river

Zip Code:

11792

Contact Information

First Name:

Middle Name:

Last Name:

Phone:

Email:

Alleged Violation Location

Date of Violaton(s):

09/19/2026

County:

SUFFOLK

Street Address:

69 Meadow Ct.

State:

NY

Latitude:

Service Territory:

KeySpan Gas East Corporation d/b/a National Grid

City:

wading river

Zip Code:

11792

Longitude:

Affected/Damaged Facility

Impacted on Facility	Facility
Yes	High Pressure Plastic Gas

Project	
✓ Was Excavation Occurring	Nature of Project: Contractor
Method of Excavation:	Backhoe
Description of Project:	Vista Contractors Corp damaged a 1/2" HDPE gas service with a backhoe while digging a foundation for a new garage.
	Other:

Enforcement	
One Call Ticket:	
Code Section:	753-3.1(a)(1)

Brief Summary of info below: Vista Contractors Corp., was digging a trench for a garage foundation without an 811 ticket. While digging with a backhoe (although he claims shovels were used), he struck and damaged the unmarked ½” HDPE gas service line.

Arrival Date and Time: **9/19/26 @ 4:52 pm**

Address Where Damage Occurred: **69 Meadow Path, Wading River, NY 11792**

Departure Time: **9/19/26 @ 5:15 pm**

Date & Time Damage Occurred: **9/19/26 @ 11:29 am**

Public Safety Commission on site: **NO**

Was Fire and/or Police onsite: **NO**

Witnessed by: **Freddy Portillo (Premier locator) / Donald Proniewych - (631) 637-286**

Contractor Name: **Vista Contractors Corp.**

Address: **106 Crescent CT, Wading River NY 11792**

Ticket Number (if known): **NO TICKET**

Start Date of Ticket: **NO**

Markout Video Link or /Picture location (if available): **NO**

Problem Locate submitted for location: **NO**

Number of Workers on site: **(3) Joeseeph Alfano (homeowner), (2) workers**

Number of Contractor's Trucks/Machinery: **(1) backhoe**

Damage Caused By: **backhoe**

Did Contractor try to do an illegal repair: **NO**

Did damage cause disruption of service to customers: **YES – (if yes, how many): (1) house: 69 Meadow Path, Wading River**

Contractor's USDOT Number (if known): **2297846 (Vista Contractors Corp - Maria Inacio, (CEO)**

Utility Company on Site: **National Grid**

Grid Number (**Gas/Electric only**): **075 56 9111**

Number of Utility Workers on site: **(1) NG responder: Mike McKenna**

Number of Utility Trucks/Machinery: **(1) truck**

Type of Utility Damaged: **½” HD PE gas service**

Approx. Length of Utility to be repaired: **1’ of ½” HD PE gas service filler, (2) electro fused couplings**

Incident: Vista Contractors Corp. was digging for a foundation for a new garage at 68 Meadow CT, Wading River. While digging without an 811 ticket the contractor struck and damaged a ½” HDPE gas service to the residence.

The homeowner who claimed to work for LILCO prior was trying to take responsibility for the damage saying he did it with a shovel. After investigating and examining the damaged piece we determined this in fact was pulled with the excavator on site and not damaged with a shovel. He was advised of the 811 call-in requirements, Code 753, and the requirement that both contractors and homeowners obtain utility markouts before beginning any excavation. It is recommended that RECONN be sent to this address/location.

I performed a database search on ISITE back to March 1, 2026, and there were no other 811 markout tickets for this location/address other than the NGrid emergency ticket (262620097) called for this damage.

Photos attached and video (if available)

Entity Details	
ENTITY NAME: VISTA CONTRACTORS CORP FOREIGN LEGAL NAME: ENTITY TYPE: DOMESTIC BUSINESS CORPORATION SECTION OF LAW: 402 BCL - BUSINESS CORPORATION LAW DATE OF INITIAL DOS FILING: 02/22/2001 EFFECTIVE DATE INITIAL FILING: 02/22/2001 FOREIGN FORMATION DATE: COUNTRY: SUFFOLK JURISDICTION: NEW YORK, UNITED STATES	DOS ID: 2608622 FICTITIOUS NAME: DURATION DATE/LATEST DATE OF DISSOLUTION: ENTITY STATUS: ACTIVE REASON FOR STATUS: INACTIVE DATE: STATEMENT STATUS: CURRENT NEXT STATEMENT DUE DATE: 02/28/2027 NFP CATEGORY:
ENTITY DISPLAYNAME HISTORYFILING HISTORYMERGER HISTORYASSUMED NAME HISTORY	
Service of Process on the Secretary of State as Agent	
The Post Office address to which the Secretary of State shall mail a copy of any process against the corporation served upon the Secretary of State by personal delivery:	
Name: THE CORPORATION	
Address: 106 CRESCENT CT, WADING RIVER, NY, UNITED STATES, 11792	
Electronic Service of Process on the Secretary of State as agent: Not Permitted	
Chief Executive Officer's Name and Address	
Name: MARIA INACIO	
Address: 106 CRESCENT CT, WADING RIVER, NY, UNITED STATES, 11792	
Principal Executive Office Address	
Address: 106 CRESCENT CT, WADING RIVER, NY, UNITED STATES, 11792	

CUSTOMER ADDRESS
TOWN WADING RIVER HSE. NO. 7 STREET MEADOW CT. C.P.R. NO. 515835

GAS SERVICE LOCATION
STREET S MEADOW CT QUAD 075568191

CROSS STREET 138' w/o MEADOW PATH PREMISES USED AS RES

SERVICE: New — Replaced — Full — Partial — Stub — Branch — Retired — Transf. — Relocation

PRESSURE: PRESSURE TEST: AIR @ 200 PS CURB COCK INSTALLED: ☐ YES ☒ NO
☐ Low (5" W.C.)
☒ High 124 TIME: Hr. Min 20 CURB COCK LOCATION (IF NONE, PROPERTY LINE) COMMON TRENCH
139L 110R 25M ☒ YES ☐ NO

PIPE FOOTAGE SIZE MATERIAL DEPTH OF MAIN NA inches
Main to PL 25 1/2" B.P.S.T
PL to Meter 240' 1/2" B.P.S.T
W.O. NO.
BUSINESS DISTRICT ☐ YES ☐ NO TAX DIST.

FOREMAN STEELE DATE 6-3-02 TAP SIZE NA

CATHODIC PROTECTION INFORMATION

A Is cathodic protection required?
☐ YES * ☒ NO
* If YES, complete "B"
B Insulator device at meter ☐ YES ☐ NO
Insulator device at main: ☐ YES ☐ NO
Anode installed: ☐ YES ☐ NO Voltage

FC-10836.1-55 2002

GAS SERVICE RECORD

















